



# TIME OF TRANSFER INSPECTION TOT# 9247 SCOTT BROWN CERT # 1679

### Site Information

Parcel Description: **13-35-202-001**  
Address: **14610 330TH ST, Strawberry Point, IA 52076** County: **Clayton**

### Owner Information

Property is owned by a business: **Yes**  
Business Name: **SHAMROCK VALLEY PROPERTIES LLC**  
Owner Name:  
Email Address:  
Address: **14610 330TH ST, Strawberry Point, IA 52076**  
Phone No:

### Additional Contact Information

Name	Email Address	Affiliate Type
<b>LUKE SCHRADER</b>	<b>luke@shraderauction.com</b>	<b>Realtor</b>

### Site related information

No Of Bedrooms: <b>7</b>	Inspection Date: <b>03/15/2024</b>
Facility Type: <b>Residential</b>	Currently Occupied: <b>Yes</b>
Last Occupied:	System Installation Date: <b>04/15/2009</b>
Permit issued by County: <b>Yes</b>	Permit Number: <b>2579</b>
All plumbing fixtures enter septic system: <b>Yes</b>	County contacted for records: <b>Yes</b>
Property Information Comments:	

### Primary Treatment

#### Tank 1

Tank Name: <b>Tank 1</b>	Type: <b>Septic Tank</b>	Tank Size (Gal): <b>2000</b>
Tank Material: <b>Concrete</b>	Tank Corrosion Type: <b>Slight</b>	Liquid Level Type: <b>Normal</b>

No. of Compartments: <b>2</b>	Pump Tank Chamber: <b>Yes</b>	Licensed Pumper Name: <b>BILL DOWNS ST49</b>
Date Pumped: <b>3/15/2024</b>	Meets Setback to Well: <b>Yes</b>	Well Type: <b>Private</b>
Distance To Well (Ft.): <b>50+</b>	Is Accessible: <b>Yes</b>	Lid Intact: <b>Yes</b>
Risers Intact: <b>Yes</b>	Effluent Filter Present: <b>Yes</b>	Watertight: <b>Yes</b>
Tank/Vault Pumped: <b>Yes</b>	Inlet Baffle Present: <b>Yes</b>	Outlet Baffle Present: <b>Yes</b>
		Functioning as Designed: <b>Yes</b>
Tank Comments:		

**Tank 2**

Tank Name: <b>Tank 2</b>	Type: <b>Holding Tank</b>	Tank Size (Gal): <b>250</b>
Tank Material: <b>Concrete</b>	Tank Corrosion Type: <b>None</b>	Liquid Level Type: <b>Normal</b>
No. of Compartments: <b>1</b>	Pump Tank Chamber: <b>Yes</b>	Licensed Pumper Name: <b>BILL DOWNS ST49</b>
Date Pumped: <b>3/15/2024</b>	Meets Setback to Well: <b>Yes</b>	Well Type: <b>Private</b>
Distance To Well (Ft.): <b>50+</b>	Is Accessible: <b>Yes</b>	Lid Intact: <b>Yes</b>
Risers Intact: <b>Yes</b>	Effluent Filter Present: <b>No</b>	Watertight: <b>Yes</b>
Tank/Vault Pumped: <b>Yes</b>	Inlet Baffle Present: <b>No</b>	Outlet Baffle Present: <b>Yes</b>
		Functioning as Designed: <b>Yes</b>
Tank Comments:		

General Primary Treatment Comments:

Distribution Type

**Siphon / Flout 1**

Label: <b>Siphon / Flout 1</b>	Material Type: <b>Manufactured</b>	Device Type: <b>Siphon</b>
Accessible: <b>Yes</b>	Functioning As Designed: <b>Yes</b>	

General Distribution System Comments :

Secondary Treatment

**Sand Filter1**

Filter Type: <b>Subsurface</b>	Distribution Type: <b>Header Pipe</b>	Material Type: <b>Rock and PVC Pipe</b>
Absorption Area: <b>1250</b>	System Hydraulic Loaded: <b>Yes</b>	Gallons Loaded: <b>300+</b>
Discharge At Time of Inspection: <b>No</b>	CBOD Results:	TSS Results:
Disinfection Present: <b>No</b>	Disinfection Type:	Tertiary Treatment Present: <b>No</b>
Tertiary Treatment Type:	Meets Setback to Well: <b>Yes</b>	Well Type: <b>Private</b>
Distance To Well (Ft.): <b>100+</b>	Sand Filter Probed: <b>No</b>	Vent(s) Located: <b>Yes</b>
Saturation or Ponding Present: <b>No</b>	Grass Cover Over System: <b>Yes</b>	Outlet Found: <b>Yes</b>

Sample Taken: **No**

GP4 Permitted: **No**

GP4 Required: **No**

System Located on Owner Property: **Yes** Easement Present: **N/A**

Functioning as Designed: **Yes**

Comments:

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: **PUMPED SEPTIC TANK AND DOSING TANK. TANKS LOOKED GOOD. SIPHON FLOAT WAS NOT ATTACHED, CHECKED DISCHARGE PIPE-NO FLOW. SYSTEM IS IN GOOD WORKING ORDER.**



**TIME OF TRANSFER INSPECTION TOT# 9247 SCOTT BROWN CERT # 1679**

Owner Name: **SHAMROCK VALLEY PROPERTIES LLC**

Address: **14610 330TH ST , Strawberry Point , IA 52076**


County: **Clayton**

Inspection Date: **03/15/2024**


Submitted Date: **3/22/2024**

**This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).**

Faxed 5-3-10 Faxed 12-8-10



# Brown's Pump Service & Excavating



Date: 4/15/09

Phone: 563-633-3365 · Fax: 563-633-9701 · P.O. Box 89 · 638 Upper St., Arlington, IA 50606

Customer: John A. Cantwell  
Address: 14642 330th St ST Pt  
14610

Job Description:  
TO HYDRANT  
REPAIR  
O vent

